

If This, Then That

In some instances, we come across a service call that has an apparent item that has failed i.e. a left hinge, primary door switch, etc. When these items fail, we highly recommend replacing additional items along with it. Below is a short list of items that should be replaced alongside the failed ones.

Failed parts	Recommended additional part/s to be replaced
Left Hinge	Right Hinge All 3 switches
Right Hinge	Left Hinge All 3 switches
Switch	All 3 switches
1 Door hinge Spring	Replace each spring on each side
Card Reader	Cable for card reader
Brunt H.V. Transformer	Capacitor (same circuit only) Diode (same circuit only) Magnetron (same circuit only)
20A Fuse (F3)	Inspect the microwave circuit to see what cause the fuse to blow. Inspect the anode relay for burnt contacts. NGO = K8, NGC = K2